

Wind Turbine Remote Visual Inspection Solutions

Protect your wind turbine's critical mechanical parts with our advanced RVI equipment, intelligent software solutions, and expert field support services

The power of wind

By generating low-emission, economical energy, wind power leads efforts to achieve a low-carbon or net zero future for our planet. With wind farm construction complete, the greatest cost associated with wind power generation involves maintaining the turbine and associated equipment. Wind conditions and environmental debris put considerable stress on a wind turbine's critical mechanical parts gradually impairing performance and driving up operating and maintenance costs over time. As such, wind turbines require periodic inspections and repairs to achieve their standard lifespan—typically about 20 years.

Predict and prevent

Waygate Technologies offers a proven range of remote visual inspection (RVI) solutions and expert field support to efficiently evaluate and combat ongoing machine wear. From software that lets you identify problems before they arise to hardware backed by decades of ingenuity, our solutions help maintain plant asset integrity and mitigate costly shutdowns.

With our RVI technology, you can gain an accurate and detailed understanding of the actual condition of your wind turbine's gearbox and other parts as they change over time. Our analysis tools put a wealth of information at your fingertips, helping you predict equipment wear, avoid failures and minimize downtime for both planned and unplanned maintenance events.

The best technology is grounded in knowledge.

If you can predict, you can prevent.

Connections drive solutions.

Intelligent Machines provide data for smarter decision making.

Advanced Analytics reflect our commitment to integrating intelligence into software.


People at Work rely on our technology to help solve problems quickly.

The drivetrain is priority #1


To boost wind farm return on investment (ROI), maintenance costs must be reduced while turbine availability stays high. About 60% of those maintenance costs come from the wind turbine's drivetrain, where the gearbox transforms slow speed, high torque wind turbine rotation to the higher speeds required by the generator, which converts the mechanical power to electricity.

Gearbox issues

Most wind farm operational expenses are related to maintaining and replacing the drivetrain's gearbox, along with production losses due to a non-functioning gearbox.



Typical % operating and maintenance cost.



Inspection solutions from Waygate Technologies

When climbing a 100-meter tower to inspect a wind turbine gearbox, a lightweight, portable video borescope is essential. Designed for tightly confined inspections, Waygate Technologies' compact, high-performance video borescopes deliver sharp, clear digital images. In addition, they feature advanced intelligent software solutions such as Menu Directed Inspection (MDI), which improves quality and productivity through:

- Automatic and consistent context tagging of captured image and video files for added data integrity without the need for manual note taking
- Guided inspections that shorten the learning curve, reduce inspection variability, and decrease errors
- Automatic inspection report generation
- Faster inspections and easier data sharing









Intermediate- and high-speed stage bearings

The Problem: The failure of a high- or intermediate-speed bearing can lead to damage of other gearbox parts, and in some cases the entire gearbox may need to be replaced. The root cause of this bearing damage is myriad and can include misalignment between the high-speed shaft and the connected generator as well as foreign object, lubrication oil viscosity, and cleanliness issues.

Our Solution: Waygate Technologies' video borescopes offer superior image quality, state of the art image processing tools, and an intuitive user interface, making it easier to inspect, detect and monitor minor flaws on the intermediateand high-speed shaft, the bearings' roller surface, and the inner and outer race. These advanced tools combined with the ability to upload rich data to the InspectionWorks Insight platform help to predict potential damage and prevent it from spreading to other components.

Planetary stage bearings

The Problem: The planetary gear and the planetary stage bearings serve to absorb varying wind stress. However, limited planetary stage space due to gear dimensions means that bearings used here generally have shortened component life. **Our Solution:** Waygate Technologies offers a wide selection of semi-flexible guide tubes giving the user more control and stability to navigate the challenging planetary gears.

Gear teeth

The Problem: Another common failure point for a gearbox is a broken gear tooth, which can be caused by material quality, surface grinding, or hardening process issues.

Our Solution: Videoscopes are needed to conduct a visual inspection of gear teeth—especially those on the low-speed shaft gear, the planetary gear, and the ring gear. Our near-focal optical tips greatly aid in the inspection of gear teeth, allowing very small flaws to be detected.



Wind Turbine Gearbox RVI Solutions Portfolio

Waygate Technologies offers a full range of innovative remote visual inspection (RVI) systems designed to fit your specific inspection needs and budget.

Key features:

- Portable, lightweight, rugged, and versatile (from 3.8 lbs. to 6.75 lbs.)
- Gesture based touchscreen with intuitive user interface (3.7 to 6.5 inch)
- Rugged construction
 (IP65, MIL-810G, and MIL-461F STD compliant)
- XpertSteer probe articulation
- Menu Directed Inspection (MDI) software that guides inspectors through the inspection process, intelligently names files and tags files, and creates inspection reports

Benefits:

- Portability especially important when climbing the wind tower
- Delivers greater probability of detection (POD) through enhanced image quality
- · Stands up to severe environments
- · Allows for precise articulation control
- · Provides guided inspection and automatic reporting





Mentor Visual iQ Video Borescope technology

This revolutionary RVI tool delivers the versatility needed for fast, efficient and accurate decision making. Ideal for inspecting bearings, gearboxes, generators, pipes and blades, the MViQ delivers a wide range of advanced features including Real3D on-demand probes that easily reconfigure probe diameter and length, 3D on-demand Phase Measurement, and real-time video streaming for live inspection collaborations.

Mentor Visual iQ Analyze

Achieve precise inspections

Our powerful TrueSight[™] imaging and analysis software delivers extreme image quality for increased probability of detection (PoD).

Mentor Visual iQ Touch

Boost inspection productivity

This highly capable borescope is designed for exceptional inspection productivity with QuickChange probes and a intuitive touch-screen interface.

Mentor Visual iQ Inspect

Get cost-effective advanced inspection capability

This value-priced offering provides excellent image quality, a streamlined user interface, and Wi-Fi and Bluetooth connectivity.

XL Series Video Borescope technology

Protect valuable industrial assets and lower maintenance costs with powerful and accurate video borescope inspection technology from Waygate's XL Series. Ideal for inspecting bearings, gearboxes, generators, pipes and blades, the XL Series provides industry leading image quality in a compact and rugged design.

XL Flex | XL Flex +

Gain ROI with greater inspection efficiency

Our versatile MDI 2.0-enabled video borescope offers stereo measurement capability, best in class image quality, and up to 4 hours of battery life. The XL Flex + model features a 3X brighter 5-inch display.


XL Detect | XL Detect +

Improve and validate inspection quality

Complete inspections with unrivaled image clarity, featuring a display that is 85% larger and 3X brighter (3.7" and 5" options).

Intelligent software for smart decisions

Get the most from your inspection data with InspectionWorks.



Advanced turbine blade inspection solutions for critical care in hard-to-reach places



Visual inspection shows the actual condition inside the blades.

Because they are subjected to tremendous aerodynamic forces, turbine blades can suffer fatigue-related damage, particularly crack-forming delaminations. High blade-tip velocities can erode the blade's leading edge, while constant stall on the trailing edge can degrade the laminates. Waygate Technologies offers equipment rental and fullservice solutions to meet your specific needs. Equipped with a large inventory of the latest inspection technologies including robotic crawlers, video borescopes and a variety of pan-tilt-zoom cameras— highly experienced field technicians can help you effectively examine your turbine blades for irregularities, especially those between the skin laminate and load-carrying main spar. Our robotic crawlers thoroughly survey any blade shear using visual inspection to help ensure proper blade balance and bending resistance.

Product Kit Technical Details

Mentor Visual iQ Wind Kits

3.9mm MViQ Wind Kit		
Kit Part Number:	MVIQCS3930-WIND	
BOM:		
Model	Description	
MVIQCS3930-9250	MVIQ INSPECT, 3.9mm x 3m in carry on case	
MVIQ-TOUCHSCRN	Touch screen feature addition	
PXT480SG	3.9mm side view brown tip	
PXT490SN	3.9mm side view red tip	
MVIQABATT	2-hour battery pack	
XA-CLEANKIT	Optical tip cleaning kit in hard case	
GTD-400S	Flexible guide tube with 4mm gripper	
MVIQ-MDI	Menu directed inspection software enhancement	

4.0mm MViQ Wind Kit Kit Part Number: MVIQCS4030-WIND Includes: Model Description MVIQCS4030-CO MVIQ inspect flame 4.0mm x 3.0m in carry on case MVIQ-TOUCHSCRN Touch screen feature addition T40120SF 4.0mm side view blue tip T40115FN 4.0mm forward view black tip T40115SN 4.0mm side view red tip MVIQABATT 2-hour battery pack XA-CLEANKIT Optical tip cleaning kit in hard case GTD-400S Flexible guide tube with 4mm gripper Menu directed inspection software enhancement MVIQ-MDI

6.1mm MViQ Wind Kit

Kit Part Number: MVIQCS6130-WIND

Includes:

Model	Description	
MVIQCS6130-CO	MVIQ Inspect Flame 6.1mm x 3.0m in carry on case	
MVIQ-TOUCHSCRN	Touch screen feature addition	
XLG3T61120SG	6.1mm side view blue tip	
XLG3T61120FG	6.1mm forward view black tip	
MVIQABATT	2-hour battery pack	
XA-CLEANKIT	Optical tip cleaning kit in hard case	
GTD-600S	Flexible guide tube with 6mm gripper	
MVIQ-MDI	Menu directed inspection software enhancement	

XL Detect and XL Flex+ Wind Kits

3.9mm XL Detect Wind Kit		
Kit Part Number:	XLDEA3930-WIND	
BOM:		
Model	Description	
XLDEA3930-9270	3.9mm x 3.0m XL Detect VideoProbe	
PXT480SG	3.9mm side view brown tip	
PXT490SN	3.9mm side view red tip	
XLGOABATTB	4-hour battery pack	
XLDE-MDI-11	Menu directed inspection software enhancement	
XA-CLEANKIT	Optical tip cleaning kit in hard case	
GTD-400S	Flexible guide tube with 4mm gripper	

3.9mm XL Flex+ Wind Kit Kit Part Number: XLFPA3930-WIND Includes: Model Description XLFPA3930-9331 3.9mm x 3.0m XL Flex+ VideoProbe system PXT480SG 3.9mm side view brown tip PXT490SN 3.9mm side view red tip XLGOABATTB 4-hour battery pack XLFL-MDI-20 Menu directed inspection software enhancement XA-CLEANKIT Optical tip cleaning kit in hard case GTD-400S Flexible guide tube with 4mm gripper

4.0mm XL Flex+ Wind Kit		
Kit Part Number:	XLFPA4030-WIND	
Includes:		
Model	Description	
XLFPA4030	4.0mm X 3.0m XL Flex+ system	
T40120SF	4.0mm side view blue tip	
T40115FN	4.0mm forward view black tip	
T40115SN	4.0mm side view red tip	
XLGOABATTB	4-hour battery pack	
XLFL-MDI-20	Menu directed inspection software enhancement	
XA-CLEANKIT	Optical tip cleaning kit in hard case	
GTD-400S	Flexible guide tube with 4mm gripper	

6.1mm XL Flex+ Wind Kit Kit Part Number: XLFPA6130-WIND Includes: Model Description XLFPA6130 6.1mm X 3.0m XL Flex+ system XLG3T61120SG 6.1mm side view blue tip XLG3T61120FG 6.1mm forward view black tip XLGOABATTB 4-hour battery pack XLFL-MDI-20 Menu directed inspection software enhancement XA-CLEANKIT Optical tip cleaning kit in hard case GTD-600S Flexible guide tube with 6mm gripper



Copyright 2020 Baker Hughes Company. All rights reserved. BHCS38574 (10/2020)

waygate-tech.com